

SAINI AUTO SPARES



177, Kohat Enclave, Pitam Pura, Delhi-110034, INDIA. Ph : 011-28833161 Fax : 011-28877116 Mobile : 09212403662to5,
E-mail : sainiexports@gmail.com, sainiauto@gmail.com, sainibrakes@gmail.com Website:www.brakesofindia.com

S. No.	Product Picture	Product Description	SAINI No.	OE No.	List Price	Type	Bore Dia	Application
1		BOOSTER DIAPHRAM	90112		300	JAPANESE		EICHER CANTER 10.90 OLD MODEL
2		MASTER CYLINDER	20021	MB295340	1300	JAPANESE	1.1/8"	EICHER CANTER 10.90 ALL MODELS
		REPAIR KIT WITH PISTON & SPRING	201021		380			
		RUBBER REPAIR KIT	201022		100			
3		CLUTCH MASTER CYLINDER	50010	MB334520	800	JAPANESE	5/8"	EICHER CANTER 10.90 OLD MODEL
		REPAIR KIT WITH PISTON & SPRING	501010		160			
		RUBBER REPAIR KIT	501011		40			
4		CLUTCH MASTER CYLINDER	50021	MC113030	800	JAPANESE	7/8"	EICHER CANTER 10.90 NEW MODEL
		REPAIR KIT WITH PISTON & SPRING	501021		200			
		RUBBER REPAIR KIT	501022		40			
5		CLUTCH MASTER CYLINDER	50022	29066463	800	TVS	7/8"	EICHER CANTER 10.90 NEW MODEL
		REPAIR KIT WITH PISTON & SPRING	501021		200			
		RUBBER REPAIR KIT	501022		40			
6		SLAVE CYLINDER	56004	ME602333	500	JAPANESE	5/8"	EICHER CANTER 10.90 OLD MODEL
		REPAIR KIT WITH PISTON & SPRING	507004		110			
		RUBBER REPAIR KIT	507005		50			
7		SLAVE CYLINDER	56005	ME601290	500	JAPANESE	5/8"	EICHER CANTER 10.90 OLDEST MODEL
		REPAIR KIT WITH PISTON & SPRING	507006		110			
		RUBBER REPAIR KIT	507007		50			
8		SLAVE CYLINDER	56021	ME602994 ME602995	550	JAPANESE	7/8"	EICHER CANTER 10.90 NEW MODEL
		REPAIR KIT WITH PISTON & SPRING	507021		130			
		RUBBER REPAIR KIT	507022		50			
9		SLAVE CYLINDER	56022	29066464	550	TVS	7/8"	EICHER CANTER 10.90 NEW MODEL
		REPAIR KIT WITH PISTON & SPRING	507021		130			
		RUBBER REPAIR KIT	507022		50			
10								